

## Menu

HISTORY FILE MAP for year 2005


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

358.04:51-04:57 6m realtime 1024bps TM lost due to long 1-way to 2-way transition at DSS-54. No DR raised.



358.05:06-05:18 12m realtime 1024bps TM lost due to long 2-way to 1-way transition at DSS-54. DR M103530 refers.

356.10:47-11:15 28m realtime 1024bps TM lost due to DSS-24 antenna halt. DSS-25 was brought in to minimize impact until DSS-24 returned to service (356.12:16). DR G106361 refers.